



(formerly Danby of North America, Inc.)

List of Completed Projects

Location	Pipe Diameter (in)	Pipe Quantity (ft)	Type	Description
Lanham, Maryland Washington Suburban Sanitary Commission	15"	630'	RCP	Severe H2S corrosion Sections of crown missing
San Jose, California	42"	437'	Concrete	Crown corrosion
Ottawa, Canada	48"	250'	Brick	Difficult access, deformed
Longwood, Florida	72"	12' Deep	Concrete	Wet well, corrosion
West Palm Beach, Florida	72"	28' Deep	Concrete	Wet well; extreme corrosion
Miami, Florida	60"	12' Deep	Concrete	Manhole
	48"	6' - 12" Deep	Concrete	Seven manholes
Van Nuys, California	18"	600'	Concrete	18" Storm drain
San Jose, CA	42"/48"	1221'/2420'	Concrete	Crown corrosion
	48"	10' Deep	Concrete	Manhole
Ottawa, Canada	60"	722'	Brick	Badly deformed/corroded
Downey, CA	78"	590'	Concrete	Crown corrosion
Jesup, Iowa	10"	390'	Clay	Cracked, badly deteriorated
Lake Worth, Fla.	48"	6' - 10'	Concrete/Brick	3 Manholes
Norfolk, VA	48"	8' Deep	Brick	3 Manholes (poor condition)
Ottawa, Canada	27"/30"	880'	RCP	H2S crown corrosion
Brookline, MA	78"	600'	RCP	Lined bottom half
Manteca, CA	42"	210'	RCP	Storm drain
Hampton, VA	42"	1910'	RCP	H2S crown corrosion
Oakland, CA	105"	352'	RCP	Crown corrosion
San Francisco, CA	50"x34"	338'	Brick	Mortar Missing
	27/28"	917'	RCP/Brick	Leaking, Corrosion
San Jose, CA	54"x36"	6,300'	Brick	Structural lining
Los Angeles, CA	69"	104'	RCP	Leaking joints



(formerly Danby of North America, Inc.)

List of Completed Projects

Location	Pipe Diameter (in)	Pipe Quantity (ft)	Type	Description
Houston, TX	48"	1,100'	RCP	H2S Corrosion
Pearl Harbor, HI	48"	260'	RCP	Oil Infiltration
San Diego, CA	102"	1,200'	RCP	H2S Corrosion (Top 240° Lined)
Dallas, TX	60"	280'	RCP	H2S Corrosion
Fair Lawn, NJ	24"	1350'	Clay	Cracked, Leaking
Fresno, CA	63"	300'	RCP	H2S Corrosion
Modesto, CA	48"	100'	RCP	H2S Corrosion
Atlanta, GA	99"x66"	100'	Brick	Stabilize Old Structure
Dallas, TX	48"	4,600'	RCP	H2S Corrosion
San Jose, CA	66"/72"	2560'/2110'	RCP	H2S Corrosion
San Jose, CA	36"	120'	RCP/Siphon	H2S Corrosion
Ottawa, Canada	72"	867'	Concrete/Brick	H2S Corrosion
Los Angeles, CA	66"/69"	204'	RCP/Siphon	H2S Corrosion
Orlando, FL	36"	200'	CMP/Storm	Corrosion
Orlando, FL	66"	500'	RCP	Leaking Joints
Los Angeles, CA	60"x70"	3750'	Concrete	H2S Corrosion
Los Angeles, CA	45"	5200'	RCP	H2S Corrosion
Los Angeles, CA	30"	900'	RCP	H2S Corrosion
Houston, TX	60"	1106'	CIPCP	H2S Corrosion
LA County, CA	54"/57"	Siphons	RCP	H2S Corrosion
Ottawa, Canada	54"	200'	RCP	H2S Corrosion
Houston, TX	108"/120"	750'	CIPCP	Cracked Storm 1
LA County, CA	54"/60"	Siphons	RCP	H2S Corrosion
Houston, TX	78"	8300'	CIPCP	H2S Corrosion
Manteca, CA	48"	850'	CIPCP	Irrigation H2O Pipe



(formerly Danby of North America, Inc.)

List of Completed Projects

Location	Pipe Diameter (in)	Pipe Quantity (ft)	Type	Description
LA County, CA	66" SE	1305'	CIPCP	H2S Corrosion
San Antonio, TX	58/60/66"	654'	CIPCP	H2S Corrosion
Edison, NJ	54"	440'	RCP	Cracked Storm
LA County, CA	66"	1800'	RCP	H2S Corrosion
San Jose, CA	66"	1600'	RCP	H2S Corrosion
Edison, NJ	54"	850'	RCP	Cracked Storm
Boise, Idaho	72"x44"	203'	CMP	Invert Corroded
Canton, IL	120"	384'	CMP	Structural
Covington, GA	78"	90'	CMP	Culvert/Deteriorated
Mexico City, Mexico	72"	700'	RCP	H2S Corrosion
Mexico City, Mexico	72"	500'	RCP	H2S Corrosion
Coos Co., OR	72"& 84"	215'	CMP	Culvert/Deteriorated
Guadalajara, Mexico	114"x84"	725'	CIPRC	H2S Corrosion
Orlando, FL	82"x50"	350'	CMP	Culvert/Deteriorated
Baltimore, MD	108"x40"	275'	Stone	Structural Repair
Mexico City, Mexico	96"	2300'	RCP	H2S Corrosion
Yokohama, Japan	112"	80'	RCP	H2S Corrosion
Binghamton, NY	66"	400'	RCP	HASMAT Site/Storm
Binghamton, NY	63"x72"	55'	Stone	HASMAT Site/Storm
Acapulco, Mexico	42"	1200'	RCP	Culverts & Storm
Japan	94"	287'	RCP	Deteriorated
Houston, TX	78"	5000'	CIPCP	H2S Corrosion
Houston, TX	72"/78"	5000'	CIPCP	H2S Corrosion
Atlanta, GA	60"/48"	260'	CMP	Structural Damage
Ixtapan, Mexico	48"	535'	RCP	H2S Corrosion
Haverstraw, NY	72" x 48"	80	CMP	Invert Deterioration



(formerly Danby of North America, Inc.)

List of Completed Projects

Location	Pipe Diameter (in)	Pipe Quantity (ft)	Type	Description
Orange Co., CA	36"	226'	RCP	H2S Corrosion
Albany, NY	72"	400'	CI Tunnel	Use Conversion
Mexico City, Mexico	48"	300'	RCP	H2S Corrosion
Santa Clarita, CA	66"	460'	RCP	Cracked
Orinda, CA	60"	1080'	CMP	Invert Eroded
Albany, NY	60"	460'	CMP	Corrosion & Leaking
Kingston, NY	90"x139"	210'	CMP	Invert Eroded
Washington, D.C.	90"	805'	Brick/Concrete	Longitudinal Cracks
Morelia, Mexico	60"	590'	RCP	Culvert/Deteriorated
Syracuse, NY	60"	525'	RCP	Hazmat site/storm
Baltimore, MD	7'x11'	100'	Concrete	Hazmat site/culvert